

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: MAGAZINE/LANYARD ASSEMBLY  
 ASSY P/N: SED27101417

SYSTEM: CREW ESCAPE SYSTEM

SUBSYSTEM: POLE CREW ESCAPE SYSTEM

REVISION:

PAGE 61 OF 70

| FMEA  |     | NAME, QTY & DRAWING REF DESIGNATION | CRITY | FAILURE MODE AND CAUSE  | FAILURE EFFECT ON END ITEM  | RATIONALE FOR ACCEPTANCE  |
|-------|-----|-------------------------------------|-------|---|---|---|
| REF   | REV |                                     |       |   |   |   |
| 9.1.1 |     | LANYARD ASSEMBLY (1), SED33103504   | 1/1   | <p>9.1.1 Mode: Lanyard strokes prematurely</p> <p>Cause:</p> <ul style="list-style-type: none"> <li>• Defective material</li> <li>• Broken threads</li> </ul> | <p>Unable to clear Orbiter due to improper bailout trajectory of crewmember</p> | <p>1. Design Features. The design features which minimize the probability of this failure mode are:</p> <ul style="list-style-type: none"> <li>a. The lanyards are designed to stroke at loads in a range averaging between 700 and 1000 pounds. Energy absorption features are provided that limit the loads to crewmembers and protect the pole from failure due to excessive loads.</li> <li>b. The lanyards are fabricated from Kedar webbing material which is proof-tested to 2000 pounds. A stroking (yielding) feature is provided for energy absorption and to protect the pole from excessive loads. This is accomplished by stitching the webbing material together with break-away Momek thread material. The progressive breaking of the stitches under crewmember loads provides the required energy absorption.</li> <li>c. The number of stitches and the acceptance criteria for the lanyard seams and stitches are identified on the design drawings. The materials used for fabrication are identified on the design drawings which are approved by the NASA JSC Materials Branch (ES5).</li> </ul> <p>2. Testing/Analyses.</p> <ul style="list-style-type: none"> <li>a. <u>Acceptance Tests.</u> <ul style="list-style-type: none"> <li>(1) Acceptance vibration test (AVT)                             <ul style="list-style-type: none"> <li>• Duration: 3 minutes/axis</li> <li>• Levels: 20 - 80 Hz, increasing 3dB/Octave</li> <li>80 - 350 Hz at 0.04g<sup>2</sup>/Hz</li> <li>350 - 2000 Hz, decreasing 3dB/Octave</li> </ul> </li> <li>(2) Lanyard fabrication sample tests                             <ul style="list-style-type: none"> <li>• Proof test of lanyard fabrication material to two times limit load (2100 pounds) by pull test prior to stitching</li> <li>• Stitch and seam sample pull tests performed at a 20 inch per minute up rate on a sample lanyard at the beginning of each production run to verify process control and certify procedure. Six lanyards are tested to verify 72 flight lanyards.</li> </ul> </li> </ul> </li> </ul> |

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: MAGAZINE/LANYARD ASSEMBLY

SYSTEM: CREW ESCAPE SYSTEM

REVISION:

ASSY P/N: SED27101417

SUBSYSTEM: POLE CREW ESCAPE SYSTEM

PAGE 62 LWF 70

| FMEA        |                 | NAME, QTY & DRAWING REF DESIGNATION | CRITY | FAILURE MODE AND CAUSE  | FAILURE EFFECT OR END ITEM   | RATIONALE FOR ACCEPTANCE  |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
|-------------|-----------------|-------------------------------------|-------|---|--|---|-------------|-----------------|-------------------------|---|---|----------|---|----|----------|---|----|----------|---|----|-----------|
| REF         | REV             |                                     |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
| 9.1.1       |                 | LANYARD ASSEMBLY (1), SED93703504   | 3/1   | <p>9.1.1 Mode: Lanyard strokes prematurely</p> <p>Cause:</p> <ul style="list-style-type: none"> <li>Defective material</li> <li>Broken threads</li> </ul> | Unable to clear Orbiter due to improper bailout trajectory of crewmember | <p>b. <u>Certification Tests</u>. (These tests were performed at the system level.)</p> <p>(1) Qualification acceptance vibration tests (QAVT).</p> <ul style="list-style-type: none"> <li>Duration: 5 times AVT, 15 minutes/axis</li> <li>Levels: 20 - 80 Hz, increasing 3dB/Octave<br/>80 - 350 Hz, at 0.067g<sup>2</sup>/Hz<br/>350 - 2000 Hz, decreasing 3dB/Octave</li> </ul> <p>(2) Flight random vibration tests, 48 minutes/axis, in 4 segments as follows:</p> <table border="1"> <thead> <tr> <th>Segment No.</th> <th>No. of Missions</th> <th>Vibration Duration/Axis</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>6</td> <td>173 sec.</td> </tr> <tr> <td>2</td> <td>19</td> <td>548 sec.</td> </tr> <tr> <td>3</td> <td>25</td> <td>720 sec.</td> </tr> <tr> <td>4</td> <td>50</td> <td>1440 sec.</td> </tr> </tbody> </table> <ul style="list-style-type: none"> <li>Duration: Segment dependent (48 minutes/axis)</li> <li>Levels: 20 - 150 Hz, increasing 6dB/Octave<br/>150 - 3000 Hz, at 0.03g<sup>2</sup>/Hz<br/>1000 - 2000 Hz, decreasing 6dB/Octave</li> </ul> <p>(3) Thermal testing (by analysis)</p> <ul style="list-style-type: none"> <li>Ground operations: 35 to 120°F</li> <li>Normal operations: 65 to 90°F</li> <li>Ascent/entry transients: 95°F maximum peak</li> <li>Ferry flight: Not applicable, PCES will be removed from Orbiter</li> <li>Launch/landing emergency escapes via PCES: 12 to 25°F</li> <li>Temperature (structure): 120°F maximum</li> </ul> <p>(4) Fungus (by analysis)</p> <ul style="list-style-type: none"> <li>Non-nutrient to fungi in accordance with MIL-STD-810D, method 508.3 or materials adequately treated (refer to MF0004-014C, paragraph 3.1.1.c)</li> </ul> | Segment No. | No. of Missions | Vibration Duration/Axis | 1 | 6 | 173 sec. | 2 | 19 | 548 sec. | 3 | 25 | 720 sec. | 4 | 50 | 1440 sec. |
| Segment No. | No. of Missions | Vibration Duration/Axis             |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
| 1           | 6               | 173 sec.                            |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
| 2           | 19              | 548 sec.                            |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
| 3           | 25              | 720 sec.                            |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |
| 4           | 50              | 1440 sec.                           |       |   |  |   |             |                 |                         |   |   |          |   |    |          |   |    |          |   |    |           |

PREPARED BY: H. HEISKALA

SUPERSEDING DATE:

APPROVED BY: J. PELISCHER

DATE:

R25-62

540210D  
 ATTACHMENT -  
 Page 107 of 115

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: MAGAZINE/LANYARD ASSEMBLY

SYSTEM: CREW ESCAPE SYSTEM

REVISION:

ASSY P/N: SED27101417

SUBSYSTEM: POLE CREW ESCAPE SYSTEM

PAGE 63 OF 70

| P/MEA |     | NAME, QTY & DRAWING REF DESIGNATION | CRITY | FAILURE MODE AND CAUSE  | FAILURE EFFECT OR END ITEM  | RATIONALE FOR ACCEPTANCE  |
|-------|-----|-------------------------------------|-------|---|---|---|
| REF   | REV |                                     |       |   |   |   |
| 9.1.1 |     | LANYARD ASSEMBLY (1), SED33103504   | 1/1   | <p>9.1.1 Mode: Lanyard strokes prematurely</p> <p>Cause:</p> <ul style="list-style-type: none"> <li>• Defective material</li> <li>• Broken threads</li> </ul> | <p>Unable to clear Orbiter due to improper bailout trajectory of crewmember</p> | <p>(5) Humidity (by analysis)</p> <ul style="list-style-type: none"> <li>• The PCES materials list was analyzed to certify compliance with MF0004-014, paragraph 3.1.1.e</li> </ul> <p>(6) Salt spray (by analysis)</p> <ul style="list-style-type: none"> <li>• The PCES materials list was analyzed to certify compliance with MF0004-014, paragraph 3.1.3.7</li> </ul> <p>(7) Sand/dust (by analysis)</p> <ul style="list-style-type: none"> <li>• Sand                             <ul style="list-style-type: none"> <li>- diameter 0.0031 to 0.039 inches</li> <li>- suspended sand 1.2 lbs. per cubic ft.</li> <li>- wind speed 33 ft/sec</li> <li>- hardness 7 to 8 Moh scale</li> </ul> </li> <li>• Dust                             <ul style="list-style-type: none"> <li>- diameter 0.0000039 to 0.003 inches</li> <li>- suspended dust 3.7 to 0.4 lb/cu ft</li> <li>- wind speed 33 ft/sec</li> <li>- hardness 7 to 8 Moh scale</li> </ul> </li> </ul> <p>(8) Additional certification tests/analyses</p> <ul style="list-style-type: none"> <li>• Transportation - packaging, shock, and vibration. Packaging designed and protective procedures developed in accordance with FED-STD-101</li> <li>• On/off cycle life test (by testing): PCES deployed 20 times, refer to (4) above</li> <li>• Transient vibration (by analysis)</li> <li>• Structural fatigue (by analysis)</li> <li>• Corrosion: (by analysis)</li> <li>• Handling shock, crash shock, and landing shock (by analyses)</li> <li>• Acceleration and cabin atmosphere (by analysis)</li> <li>• Full life and limited life certification (by analysis)</li> </ul> <p>c. Certification Tests at the LRU Level</p> <p>(1) Lanyard lot sample seam pull test.</p> <ul style="list-style-type: none"> <li>• Proof test of lanyard fabrication material to two times limit load (2000 pounds) by pull test prior to stitching</li> <li>• Stitch and seam sample pull tests performed at a 20 inch per minute rate on a sample lanyard at the beginning of each production run to verify process control and certify procedure. Six lanyards are tested to verify 72 flight lanyards</li> </ul> |

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: MAGAZINE/LANYARD ASSEMBLY

SYSTEM: CREW ESCAPE SYSTEM

REVISION:

ASSY P/N: SED27101417

SUBSYSTEM: POLE CREW ESCAPE SYSTEM

PAGE 64 OF 70

| FMEA  |     | NAME, QTY & DRAWING REF DESIGNATION | CRIT'Y | FAILURE MODE AND CAUSE   | FAILURE EFFECT ON END ITEM   | RATIONALE FOR ACCEPTANCE   |
|-------|-----|-------------------------------------|--------|--|--|--|
| REF   | REV |                                     |        |  |  |  |
| 9.1.1 |     | LANYARD ASSEMBLY (1), SED33103504   | I/I    | <p>9.1.1 Mode: Lanyard strokes prematurely</p> <p>Cause:<br/>                     • Defective material<br/>                     • Broken threads</p> | Unable to clear Orbiter due to improper bailout trajectory of crewmember | <p>d <u>Turnaround Test</u>: The lanyards are removed after each flight and inspected, per OMBSD requirements, prior to reinstallation for each mission.</p> <p>3. Inspection/QA/Manufacturing.</p> <p>a. All PCES fabrication, assembly, and test activities were performed under the jurisdiction of the NASA JSC Quality Assurance (QA) Division in accordance with JSCA 5312 SR&amp;QA Manual Requirements. QA surveillance was provided for procurement, planning, processing, fabrication, assembly, certification testing, and acceptance testing. Mandatory inspection points were employed at appropriate points in the fabrication, assembly and acceptance process.</p> <p>b. Receiving inspection verified that materials provided by suppliers were as identified on the procurement documents, and that data was provided attesting to the traceability and acceptability of materials and components received from suppliers.</p> <p>c. All lanyard assembly components were fabricated of aerospace approved materials and are assembled by trained technicians. QA inspections performed during the fabrication, assembly, testing, and acceptance process prior to delivery verified:</p> <ol style="list-style-type: none"> <li>(1) Use of correct, approved materials</li> <li>(2) Dimensional tolerances specified on design drawings</li> <li>(3) One hundred percent visual inspection for broken threads and fabric after assembly is stitched and verification of the number of stitches per inch</li> <li>(4) Cleaning of parts and assemblies in accordance with JSC Manual 5322, paragraph 7.1.3 to level GC</li> <li>(5) Proper application of lubricant to bearings, alignment, and fitting of bearings in accordance with drawing requirements</li> </ol> |

PREPARED BY R. HESKALA

SUPERSEDING DATE:

APPROVED BY T. PELLSCHEN

DATE:

PCES-64

ATTACHMENT -  
 Page 109 of 115

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: MAGAZINE/LANYARD ASSEMBLY

SYSTEM: CREW ESCAPE SYSTEM

REVISION:

ASSY P/N: SED27101477

SUBSYSTEM: POLE CREW ESCAPE SYSTEM

PAGE 65 OF 70

| FMEA  |     | NAME, QTY & DRAWING REF DESIGNATION | CRTY | FAILURE MODE AND CAUSE   | FAILURE EFFECTION<br>END ITEM   | RATIONALE FOR ACCEPTANCE  |
|-------|-----|-------------------------------------|------|--|---|---|
| REF   | REV |                                     |      |  |   |   |
| 9.1.1 |     | LANYARD ASSEMBLY (1), SED33103504   | U1   | <p>9.1.1<br/>Mode:<br/>Lanyard strokes prematurely</p> <p>Cause:<br/>• Defective material<br/>• Broken threads</p> | <p>Unable to clear Orbiter due to improper bailout trajectory of crewmember</p> | <p>(5) Application of part number identification in accordance with JSC-SPEC-M1</p> <p>d. <u>Turnaround</u>. The PCES end item is removed after each flight and the lanyards are visually inspected, per OMRSO requirements, prior to reinstallation for each mission. The inspections include visual examination for signs of deterioration or damage to thread or fabric, roller bearings seizing and snap-hook function.</p> <p>4. <u>Failure History</u>. The lanyard is a newly designed hardware item and has no failure history</p> <p>5. <u>Operational Use</u>.</p> <p>a. <u>Operational Effect of Failure</u>. Probable loss of crewmember.</p> <p>b. <u>Crew Action</u>. None.</p> <p>c. <u>Crew Training</u>. Crew is trained in the proper use of the lanyards.</p> <p>d. <u>Mission Constraints</u>. None. Mission would be terminated prior to use of the lanyards.</p> <p>e. <u>In-Flight Checkout</u>. None.</p> |

